1st. Pop up frame part way (short of the magnets touching) so there can be slack in the graphics. (see image to right) To attach graphics to the frame see illustrations below. It is best to start with the tabs on the top of the graphic. Rotate cap Insert silicon counter- clockwise tab into hub to remove cap from hub. Silicon Fabric Graphic Rotate cap Fabric clockwise to Graphic Insert cap Graphic lock in place. into hub

Finish. Pop up frame 100% so magnets come together and slack is eliminated from graphics.